The effect of instream logs on river bank erosion: field measurements of hydraulics and erosion rates

Nuosha Zhang^{a*} and Ian D. Rutherford^a

*Corresponding Author: Nuosha Zhang: E: nuoshaz1@unimelb.edu.au; T: +61 3 83449317; Address: 221 Bouverie Street, Parkville, VIC 3010

^a*School of Geography, University of Melbourne, Melbourne, Australia*

Running Head: Field measurements of hydraulics and bank erosion around logs

Abstract

This is the first substantial field measurement of river-bank erosion around fallen logs in rivers. Whilst numerous studies have established that living trees can stabilize river banks, and that fallen trees can cause scour of the river bed, knowledge of bank erosion effects from logs is largely restricted to qualitative observations. Recent flume studies suggest that a single log can increase near-bank velocity (and thus erosion) and this increase is related to the blockage ratio of the log and the distance between the log and bank. However, hydraulic interactions between logs can reduce this increase or even decrease the near-bank velocity. These theories, developed in a straight flume, have not been tested in the field. We measured erosion rates (relative to controls) on river-banks adjacent to 35 large logs for two years, and velocity distributions around 11 logs during a near-bankfull flow in anabranching channels of the River Murray, SE Australia. This channel has

This is the author manuscript accepted for publication and has undergone full peer review but has not been through the copyediting, typesetting, pagination and proofreading process, which may lead to differences between this version and the Version of Record. Please cite this article as doi: [10.1002/esp.4838](https://doi.org/10.1002/esp.4838)

abundant large instream logs, consistent bank material, and consistent regulated high flows. The field results generally supported the velocity changes caused by single and multiple logs in the flume studies, with single logs increasing near-bank velocity, but with the hydraulic interactions between successive logs tending to reduce this increase. Flow patterns caused by logs adjacent to curved banks were more complicated as the local effects of logs reinforced or weakened recirculating flows. Instream logs did not change overall, average, bank erosion rates, but they tended to shift the erosion from bank top to bank toe. However, individual logs increased or decreased bank erosion rates in patterns that generally concur with the near-bank velocity changes predicted in flume studies: that isolated logs increased erosion rates whilst hydraulically interacting logs did not increase erosion rates.

Keywords

Large wood; bank erosion; near-bank velocity; curved bank; recirculation flow

Introduction

In recent decades, the interaction between instream wood and river processes has been recognized (Gurnell, Piégay, Swanson, & Gregory, 2002). Instream wood causes scour and deposition and enhances complexity of river morphology (Abbe & Montgomery, 2003; Collins, Montgomery, Fetherston, & Abbe, 2012; Gurnell, Bertoldi, & Corenblit, 2012). Instream wood increases the number of pools and pool area, enhances retention of organic matters and provides habitat and nutrients for

aquatic species (Gurnell & Sweet, 1998; Montgomery, Buffington, Smith, Schmidt, & Pess, 1995; Pilotto, Bertoncin, Harvey, Wharton, & Pusch, 2014). Instream vegetation has been recognised as an ecosystem engineer that actively alters channel morphology for its benefit, usually by altering patterns of erosion and deposition (Corenblit, Tabacchi, Steiger, & Gurnell, 2007; Gurnell, 2014). As the geomorphological and ecological benefits of instream wood are recognized, many river restoration projects are now reintroducing wood to rivers after centuries of removing wood to improve flood conveyance and navigation (Abbe, Montgomery, & Petroff, 1997; Roni, Beechie, Pess, Hanson, & Jonsson, 2015). Thus, an active research question is the effect of instream wood (whether natural or artificial) on processes of erosion and deposition. This paper describes a field study of the effect of instream logs on bank erosion. As the stability of logs is a necessary condition for logs to induce geomorphological changes, we monitored hydraulic and geomorphological changes around large river redgum logs (*Eucalyptus camaldulensis*), in an Australian river, which are rarely moved even by a 1-in-20 year flood (Koehn, Nicol, & Fairbrother, 2004).

It is well established that riparian vegetation can increase bank stability by reducing soil moisture (Pollen-Bankhead & Simon, 2009) and creating a reinforced soil-root matrix (Abernethy & Rutherford, 2001). The distribution of riparian vegetation can influence the pattern of bank retreat (Pizzuto, O'Neal, & Stotts, 2010; Rutherford & Grove, 2004). Keller and Swanson (1979) described how log jams can increase or decrease bank stability depending on their position and

geomorphological setting. Lester and Wright (2009) measured bank erosion around reintroduced logs with diameter of 0.05 – 0.35 m and found that, for a short while after the logs were reintroduced, there was an average of 0.14 mm/day increase of bank erosion, but no long-term effect.

The channel morphological changes caused by instream logs are associated with the hydraulic changes caused by logs (Mutz, 2000; Wallerstein, Alonso, Bennett, & Thorne, 2001). Instream logs can act as roughness elements and generally reduce mean channel velocity (Gippel, 1995; Shields & Gippel, 1995). Instream logs can deflect flow through or away from the gap between logs and the channel boundary (bank and bed) and create high or low flow zones around the logs (Daniels & Rhoads, 2004; Zhang, Rutherford, & Ghisalberti, 2019a, 2019b). These near-boundary velocity changes can influence the boundary shear stress and erosion processes in rivers (Dietrich & Whiting, 1989). The velocity fields around individual logs or log jams are diverse and case dependent (Daniels & Rhoads, 2003, 2004, 2007; Klaar, Hill, Maddock, & Milner, 2011; Mutz, 2000).

Zhang et al. (2019a, 2019b) conducted a series of flume experiments and systematically investigated the hydraulic effect of instream logs on near-bank velocity and potential bank erosion. They found that a hydraulically isolated log increased the near-bank velocity around the log for every test and the magnitude of this increase is related to the blockage ratio and distance from the bank. When there are multiple logs in the stream, that hydraulically interact with each other, the first log

still functions the same as a single log, increasing the near-bank velocity, but then the near-bank velocity progressively decreases downstream as the flow passes the other logs. Thus, multiple logs in the flume caused less increase in the near-bank velocity than a single log, and even reduced the near-bank velocity when logs were close to the bank. This is because the drag force of the logs is suppressed when the logs are in the wake interference zone of upstream logs and therefore, they progressively deflect less flow through the gap between the logs and the bank (Knighton & Macdonald, 1979; Morris, 1955; Zhang et al., 2019b). The near-bank velocity change around multiple logs is related to spacing between logs, distance between logs and bank, and the streamwise distance from the first log.

Some hydraulic rules of thumb emerged from the flume experiments (Zhang et al., 2019a, 2019b).

- When multiple logs are more than 27 root plate diameters apart, they behave like single logs and increase near-bank velocity.
- When multiple logs are less than 17 root plate diameters apart, and with intermediate distance from the bank, they can increase near-bank velocity less than a single log,
- while at the same spacing, logs close to the bank (apart from the first log) can decrease near-bank velocity, as the gap between the log and

bank produces more resistance to flow passing through the gap when the gap becomes smaller.

- The first log of a log-group always functions as a single log.

These results were conducted in a straight flume with vertical banks.

This study investigates whether the hydraulic theory and flume results described above are useful for understanding patterns of erosion around large wood in natural rivers. Therefore, the four aims of this paper are as follows.

1. Test whether a single log (classified here as Type 1 logs), adjacent to a straight bank and with no log or other instream vegetation within 100 m upstream (close to 27 root plated diameters), increases the near-bank velocity in proportion to the blockage ratio of the log and distance between the log and the bank.
2. Test whether for multiple logs (Type 2 logs), adjacent to a straight bank and with logs or other instream vegetation within 100 m upstream, the near-bank velocity progressively decreases downstream as found in the flume study. The flume experiments only tested multiple logs with the same size, orientation and distance from the bank and thus it cannot provide accurate predictions of the magnitude of near-bank velocity change caused by multiple logs with different size, orientation and distances from banks as we found in the field.

3. Extend the measurements to situations where logs are adjacent to curved river-banks (Type 3 logs).
4. Measure if bank erosion associated with logs with various configurations, orientations, and positions is related to the hydraulic changes caused by logs.

In this study we measured the near-bank velocity field around 11 logs of the three types during near-bankfull flow in Jan 2017 and monitored bank erosion with erosion pins around 35 logs for two irrigation seasons from 2015 to 2017 in anabranching channels of the River Murray, SE Australia. The measurement results were then compared with the experimental results from flume studies.

Methods

Field site: Anabranching channels of the River Murray

It is inherently difficult to measure the effect of large logs on bank erosion in the field. First, we need to isolate the effect of the log from other erosion mechanisms. Second, most bank erosion around logs will occur when the log first falls in, and during relatively rare high flows toward bankfull. For these reasons field programs could have to wait many years before they gathered useful data. In this project we overcame these challenges by monitoring bank erosion around logs in a large channel that carries seasonally high irrigation flows. The anabranching channels of the River Murray in SE Australia (Figure 1 and 2) provide an ideal site to measure hydraulic changes and erosion associated with instream logs, since the channels

provide abundant instream logs, have relatively consistent bank material, and consistent regulated high flows during summer. **(Figure 1 near here) (Figure 2 near here)**

The River Murray is a meandering, anabranching river that forms the border between New South Wales and Victoria. The river reach between Hume Dam and Lake Mulwala (approximately 1,000 km from the river mouth) includes approximately 200 km of the main river channel in addition to a network of natural anabranching channels (Figure 1 and 2). The flow regime in the target reaches is heavily modified by Hume Dam located 40 km upstream. The regulation reduces the variability of the flow and changes the seasonal pattern of the flow regime. The natural flow regime, characterised by high winter flows and low summer flows, has been reversed so that long-duration near-bankfull flows for irrigation occur in summer, and low flows occur in winter (Figure 3). In addition, a 1-in-10 year flood occurred during the 2016 – 2017 irrigation season. The long-duration irrigation flows have led to rapid erosion of the anabranch channels (channel widening and rapid lateral migration), as well as undercutting of many large riparian trees (River Redgums, *Eucalyptus camaldulensis*) so that they have progressively fallen into the anabranch channels over the last forty years (Tilleard, Erskine, & Rutherford, 1994). River Redgums are the most widely distributed riparian trees in Australia. They are large, multi-branched trees with an average mature height of 20 m, with a canopy of similar width (Boland et al., 2006), and wood density greater than 1 g/cm³ (White, 1998). Once they have

fallen into the river, they tend to remain where they have fallen (Koehn et al., 2004) and do not form large jams. (**Figure 3 near here**)

Parlour Creek (Figure 1 and 2), one of the right-bank (northern) anabranching channels of the River Murray, is 13.2 km long, 30 to 60 m wide and 2 to 3 m deep. Chambers Creek (Figure 1), which is 6.1 km long, 15 to 30 m wide and up to 1 m deep, branches off from the main channel of the River Murray and joins Parlour Creek. Parlour Creek takes about 26% and Chambers Creek about 4% of flow from the main channel during irrigation flows (NSW Department of Primary Industries, 2013).

Flow velocity and depth was measured around all large logs in a 1.8 km section of Parlour Creek (Figure 1 and 4) that has abundant logs and good access. Erosion pins were placed around 35 logs (Figure 1) which were selected to cover a range of log size, form, orientation and distance from the bank.

Field Measurements

Log dimensions

Fallen logs in the target reaches were first identified and measured from aerial photographs (Nearmap imagery, Nov 2015, Nov 2016, Jun 2017) with resolution of 0.1 m. Measured variables included log distance from the bank, angle relative to the flow direction, length, diameter of the root plate and breast diameter of the trunk (approximately 1.3 m from the root plate). These measurements were then verified

by field measurements, and especially where the log was obscured by riparian vegetation in the aerial images. Many logs were partially submerged during low flow seasons and visual estimation of the log dimensions had to be made during the field surveys.

Hydraulics

Flow velocity and depth around logs were measured during irrigation flow in Jan 2017 when most logs were just covered by water. Under this condition we expected the logs to have the maximum influence on hydraulics. An Acoustic Doppler Current Profiler (ADCP) on a float with Differential Global Positioning System (DGPS) with sub-meter accuracy (Sontek River Surveyor S5) was used to measure the flow depth ($\pm 1\%$ accuracy) and distribution of near-bank velocity in streamwise and transverse direction ($\pm 0.25\%$ accuracy) upstream and downstream of the log with frequency of 3000 kHz. The flume experiments (Zhang et al., 2019a, 2019b) showed that near-bank velocity increase caused by logs can extend about 5 m (i.e. two root plate diameters) upstream and the maximum velocity increase occurs immediately downstream of the log. Therefore, the upstream velocity distribution (i.e. the approaching flow condition) was measured between 5 and 25 m upstream of the root plate and the downstream velocity distribution (impacted flow condition) was measured immediately downstream of the root plate (from 0 to 5 m) depending on the field conditions (Figure 4). For each velocity distribution, at least three transects

were completed for accurate time-averaged velocity measurements. (**Figure 4 near here**)

Bank erosion

Erosion was measured over two years covering two full irrigation seasons (2015 – 2017), and one flood (2016). Erosion pins were used to monitor the bank erosion around logs, which is an effective method to accurately measure bank changes over a short time scale (a few months to a few years) (Henshaw, Thorne, & Clifford, 2012; Lawler, 1987, 1993; Lester & Wright, 2009). The erosion pin method followed guidelines provided by Lawler, Grove, Couperthwaite, and Leeks (1999). The erosion pins were 30 cm long steel pins (bicycle spokes) with coloured heat-shrink tube as markers on their exposed ends (Figure 5-1). Three vertical lines of pins (referred to as ‘log pins’) were placed around the root plate where the log was the closest to the bank to measure the erosion rate effected by logs (white dots in Figure 4). One vertical line of control pins (black dots in Figure 4) was placed more than 5 m upstream of the root plate, where there was no other log or vegetation, to measure the erosion rate outside of the influence of the log. Each vertical line included four pins spaced 30 cm apart. The setup in Figure 4 indicated an ideal plan and slight variations due to the field conditions occurred. All the surveyed logs had control pins and log pins.

The log and control pins were marked with different coloured tubes. The pins were inserted to the lower edge of the coloured markers before each irrigation

season. After each irrigation season, the erosion rate (cm/yr) was measured from the current bank surface to the lower edge of the mark which indicated the bank surface before the irrigation season (Figure 5-3). The setup of the pins was designed to measure erosion; however, some pins were found buried which indicated that deposition had occurred. For the buried cases, a negative rate of erosion (Figure 5-3) was recorded (Couper, Stott, & Maddock, 2002). After the measurements of the first season on May 2016, the pins were reset with the lower edge of the mark at the bank surface and lost pins were replaced. In order to recover the erosion pins, the lower edge of the mark was set around 10 cm from the top of the pin. Therefore, changes of bank from -10 to +20 cm could be recorded. The pins could not be recovered if the erosion or deposition was higher than these ranges. 419 pins were used in 2015 and 443 pins were used in 2016. **(Figure 5 near here)**

Data analysis

Post-processing of ADCP data and calculations

When measuring velocity on the river we made an effort to keep the ADCP float moving at a constant speed and as close to a straight line as possible, however, because of the fast currents (sometimes as high as 1 m/s), the tracks of the transects were irregular. We developed algorithms in MATLAB to post-process the ADCP data to straighten the tracks and produce depth averaged velocity. The procedures in the algorithms included converting the velocity coordinate system,

projecting velocity profiles to pre-determined cross-sections, building grids (0.5 m*0.2 m, Figure 4), averaging velocities within the grid and calculating and plotting depth averaged velocity.

Comparing near-bank velocity with the predictions developed from the flume experiments

For a Type 1 log, we compared the measured average velocity in the gap between the log and the river bank with the average velocity estimated by the predictive equations developed from Zhang et al. (2019a) (Eqn. 1). The near-bank velocity increase caused by a Type 1 log can be estimated by the blockage ratio of the log and the distance from the bank (Figure 11 in Zhang et al. 2019a).

$$\Delta u_s / u_{up} = nB + m \quad (\text{Eqn. 1})$$

where Δu_s is the near-bank velocity increase caused by a single log, u_{up} is the averaged near-bank velocity upstream of the log, and n and m are empirical factors determined by the flume experiments in Zhang et al. (2019a) (Table 1). Since all root plates of logs were emergent, the blockage ratio of the log, B was calculated by:

$$B = W_r / W + (W_t / W)(D_t / D) \quad (\text{Eqn. 2})$$

where W and D is channel width and depth at the log, W_r and W_t is the channel width covered by the root plate and trunk, and D_t is the trunk diameter. **(Table 1 near here)**

For a Type 2 log, we focus on testing the *patterns* of near-bank velocity change found in the flume study (Zhang et al. 2019b). The estimate developed from the flume study is only for reference and cannot accurately predict the near-bank velocity around multiple logs with various characteristics, since it was based on logs with identical size, orientation and distance from bank. This reference of near-bank velocity change for a Type 2 log can be estimated by

$$\Delta u_m / \Delta u_s = ae^{-bl} + c \quad (\text{Eqn. 3})$$

where Δu_m is the near-bank velocity change caused by a type 2 log, Δu_s was the velocity increase caused by the first log (for which we used the measured velocity increase at the first log), l is the streamwise distance from the first log, and a , b and c are empirical factors determined by the flume experiments in Zhang et al. (2019b) (Table 2). **(Table 2 near here)**

Erosion measurement

The length measured from the bank surface to the lower edge of the mark was considered to be the erosion rate for each season (cm/year), since the measurements were taken annually. The erosion rates at the control and log were averaged within categories of channel, size (root plate diameter, trunk diameter), log form (with only a trunk, with a root plate, a trunk and main branches, with a root plate, a trunk, main branches and secondary branches), distance from the bank (attached to bank, close to bank 0-2 m, intermediate distance 2-5 m, and far from bank 5- m)

and angle to flow (parallel, oblique and perpendicular). A t-test was used to test for the significance of the difference of erosion rate between controls and around log in the same category. We accepted 0.05 as the level of significance. A relative erosion rate was calculated for each category, which was the average erosion rate around each log divided by the average erosion rate at the control. Lost pins were excluded from the analysis.

Results

Hydraulic results

Upstream and downstream velocity fields were measured around 11 logs at near-bankfull flow in Jan 2017. To summarise, single logs increased near-bank velocity, and multiple logs did not increase near bank velocity. Recirculation flows were induced around almost all logs adjacent to curved banks, and these flow patterns were modified by logs.

The hydraulic effect of instream logs on near-bank velocity

Type 1 logs (i.e. log with a straight bank close by and without any log or instream vegetation within 100 m upstream) were rare in these channels. Only two logs fitted into this group, and both logs increased near-bank velocity. The predicted velocity was 9% and 16% less than the measured velocity for logs S1 and S2, respectively (Figure 6). **(Figure 6 near here)**

There were three Type 2 logs, which were logs adjacent to straight banks and with logs or instream vegetation within 100 m upstream (Figure 6). Log M1 was located 30 m downstream of instream willow trees, log M2 was located 20 m downstream of M1, and log M3 was located 40 m downstream of log S2. Log M1 and M2 both had a small angle (less than 30 degrees) to the flow, 0.5 – 0.6 m trunk diameter and 5 – 6 m root plate diameter. As predicted, these hydraulically interacting logs either caused no change in velocity near the bank or decreased the near-bank velocity (Figure 6). The section of instream willows created a dead water zone downstream of the willows and these logs were in the wake of the instream willows. As a result, they produced almost no hydraulic changes near the bank. Since the approaching flow for log M1 and M2 recirculated, a velocity estimate could not be calculated for these logs. Log S2 and M3 were newly recruited (2016) large logs spanning more than half of the channel width (Figure 7). Some roots of log M3 were still attached to the bank, but flow was passing through the gap between the root and the bank. As predicted, log S2, as the first log in the series, increased the near-bank velocity from 0.079 to 0.24 m/s. Then, the near-bank velocity progressively decreased to 0.20 m/s between log S2 and M3, and then decreased further to 0.077 m/s at log M2, which was lower than the estimated velocity (0.14 m/s) (Figure 6). **(Figure 7 near here)**

Type 3 logs were located adjacent to curved banks, and these were the most common type of log. Five of six logs of this type were associated with recirculating flow and thus the averaged near-bank velocity in Figure 6 cannot represent the effect of logs of this type. Log C5 (Type 3), approximately 40 m downstream of M3, fell

into the channel before 2010, and a second tree on the abutment immediately upstream fell on top of C5 in 2016. C5 and the new log not only decelerated the flow near their root-plates, but they also formed a backflow near the bank adjacent to the root plate (Figure 7).

Log C3 was the only log of Type 3 that was not associated with recirculation flow. Log C3 was located at the exit of a meander bend, on the outer bank, and with a scallop shaped bank immediately upstream (Figure 8). The upstream velocity distribution for C3 was measured in the scalloped bank where the depth averaged velocity showed a hydraulically uniform flow. With uniformly distributed approaching flow, log C3 increased near bank velocity (Figure 8). As the near-bank flow upstream of log C3 was not deep enough to be measured, we used the velocity measured closest to the bank to predict the near-bank velocity around the log (dashed bars in Figure 6). The measured result was 31% greater than the predicted value. **(Figure 8 near here)**

The interactions between instream logs and recirculating flows

Many of the logs in the field were close to a curved bank-line with scallops or alcoves that generated local flow recirculation. Where the logs increased the near-bank velocity they tended to weaken the recirculation, where the log decreased the near-bank velocity they tended to reinforce the recirculation (Figure 9).

Logs that were far from the bank had no measurable influence on the recirculation flow caused by the curved bank-line. This is well illustrated by Log C6

(Figure 9-1) which was far from the bank and had no influence on the recirculating flow (Figure 9-1).

Hydraulically *isolated* logs close to the bank can increase the near-bank velocity and weaken recirculation flow. Log C4 and another downstream log doubled the average velocity of the streamwise flow between the log and the bank (Figure 9-2). This fast flow suppressed the recirculation flow and shrank the width of the backflow from 4 m upstream (c in Figure 9-2) to less than 1 m at the downstream end (d in Figure 9-2).

Hydraulically *interacting* logs close to the bank can decrease the near-bank velocity and reinforce recirculating flow. Log C5 (downstream of log M3, Figure 7) and another newly fallen log (fell in 2016) decreased the average velocity of the streamwise flow between the logs and the bank by more than 40% (Figure 9-3). This slow flow generated a backflow downstream of a small abutment which was too small to induce a recirculation flow by itself (f in Figure 9-3). **(Figure 9 near here)**

Multiple logs adjacent to a curved bank-line can induce complicated flow patterns. Log C1 and C3 were located near the outer bank of a meander bend with a large abutment close downstream (Figure 10). The mean flow velocity between the two logs (c and d in Figure 10) was close to half of the approaching flow (a in Figure 10) and was 70% downstream of log C2 (e in Figure 10). A recirculation zone formed between the bank and the root plate of each log (Figure 10). These two logs

appear to behave like two permeable groynes (Uijttewaai, 2005). (**Figure 10 near here**)

Bank erosion around fallen logs

The erosion pins were measured after one full season of high irrigation flows that were close to bankfull (Figure 3). At the start of the second period of monitoring (irrigation season starting August 2017) there was a 1-in-10 year flood. Of the 862 pins that were placed, 319 (76%) and 272 (61%) pins were recovered for the 2015 – 2016 and 2016 – 2017 seasons respectively. Among the recovered pins, 23 and 42 pins were buried for season 2015 – 2016 and 2016 – 2017, respectively. The burial of pins was more likely to be caused by fluvially transported sediment than mass failure of the top bank, as the mass failure would remove or bury the entire pins and we would not be able to recover the pins, and we did not notice signs of mass failure around the burial sites. The recovery rates were similar for control pins and erosion pins for both seasons. The recovery rate of erosion pins for our survey was comparable to Lester and Wright (2009). Some of the lost pins may be due to erosion that exceeded the inserted length (e.g. mass failure), meaning that the measured erosion rate is likely to be an underestimate. Nevertheless, there was no significant difference of recovery rates between control pins and logs pins for either season, so the lost pins had little influence on the results overall.

The average erosion rate around the 35 logs ranged from 1 cm/yr to 6 cm/yr but was consistently around 3 cm/yr (Figure 11-1). Overall, the bank erosion rate

adjacent to logs was very similar to the erosion rate of the controls (Figure 11-1). The flood in the second irrigation season produced a slightly higher erosion rate for both control and log pins. **(Figure 11 near here)**

Although the logs caused little overall change in erosion rate, they did cause changes in the vertical distribution of erosion across the bank face. The erosion rate of the control was significantly higher at bank top (position 1) than at bank toe (position 4) for both seasons (p -value = 0.0002 & 0.039), while the erosion rate adjacent to logs was evenly distributed from bank top to bank toe (Figure 11-2 and 3). This suggests that the logs shifted the erosion pattern toward the toe of the bank. Compared to the vertical redistribution of erosion, the logs did not cause significant erosion changes in the streamwise direction (Figure 11-4 and 5).

Whilst logs did not increase the average bank erosion rates, the hydraulics around logs did increase or decrease bank erosion rates around specific logs in the ways that we predicted from the flume studies. The bank erosion changes caused by logs in various categories are presented as the ratio of the averaged erosion rate of the three pin lines around a log, and at the control for that log (Figure 12). A relative erosion rate of more than one indicates that the log increased the erosion rate, whilst less than one suggests that the log decreased the erosion rate. **(Figure 12 near here)**

The logs with larger blockage ratio had a greater effect on bank erosion. In Chambers Creek, where the channel width was half of Parlour Creek, the logs in

Chambers Creek (0.59) had an average blockage ratio almost double those in Parlour Creek (0.30). The logs in Chambers Creek increased erosion rates after a season of bankfull flow and decreased erosion rate during the flood (however, these changes were not statistically significant), whereas the logs in Parlour Creek caused only small changes in erosion for both seasons (Figure 12-1).

As predicted, hydraulically isolated logs consistently increased the bank erosion rate for both seasons (Figure 12-2), whereas hydraulically interacting logs did not. These changes were close to the margin of statistical significance ($P = 0.15$ and 0.07) because of the small number of isolated logs. Twenty-eight of the 35 logs we surveyed were hydraulically interacting logs which, as predicted, did not cause significant change in bank erosion rate.

Logs at different distances from the bank produced different erosion rates. Logs attached to the bank caused no change, logs close to the bank (0-2 m) reduced the erosion rate, whilst logs at an intermediate distance from the bank (2-5 m) increased the erosion rate for both seasons, again, close to statistical significance (Figure 12-3). Logs that were positioned obliquely to the flow produced substantially more erosion than logs that were parallel or perpendicular (the difference was significant or marginally significant) (Figure 12-4).

Discussion

Hydraulics: Comparison with flume results

The field conditions including bed and bank morphology, channel features and approaching flow conditions around instream logs, were more complicated than the conditions previously tested in a flume (Zhang et al., 2019a, 2019b). However, in general the field results supported the flume results. As the near-bank flow around logs generally had a streamwise direction (Figure 7 – 10), the major effect of logs on bank erosion was to change the magnitude of the near-bank velocity rather than to steer the flow towards the bank.

The flume experiment of Zhang et al. (2019a) showed that a single log (Type 1) can increase the near-bank velocity, and that the velocity increase can be estimated using the blockage ratio of the log and the distance of the log from the bank. The predictions of the near-bank velocity for a Type 1 log were generally consistent with the field measurements. The prediction underestimated the field observations by 9% and 16% for log S1 and S2, respectively. The underestimation could be caused by the reduction of the cross-sectional area near the bank, from the upstream to downstream cross-sections (Figure 13). The difference between predicted and measured velocity for log C3 was much larger (31%) than log S1 and S2, which can be explained by the larger downstream change in cross-sectional area (Figure 13). **(Figure 13 near here)**

The field measurement also supported the theoretical proposition that logs that hydraulically interact with other logs (Type 2) can decrease the near-bank velocity. Log M1, M2 and M3 that had a spacing of four-six root-plate diameters from the upstream log or instream willows, either decreased near-bank velocity or caused almost no hydraulic changes. The near-bank velocity changes along logs S2 and M3 also support the theory from the flume studies that suggested that near-bank velocity will progressively decrease downstream along multiple logs. Log M3 decreased the near-bank velocity more than the predicted velocity. This can be explained by log M3 still having roots attached to the bank and the gap being smaller than the condition tested in the flume. Therefore, log M3 produced more resistance to flow passing through the gap and the downstream velocity was less than the reference value.

The field results show that a newly fallen log which is close to the bank and hydraulically interacts with other logs (type 2) can reduce bank erosion. However, the flume results suggest that if the erosion around the log keeps developing, and the distance between the log and bank increases to an intermediate distance (2 – 5 m), the log can then increase the bank erosion at this distance from the bank, and this rate of increase will fall beyond 5 metres (Zhang et al., 2019b). These changes of the effect of logs on bank erosion as the distance between the log and bank increases are supported by our field erosion measurements (Figure 12-3).

In summary, for type 1 logs near a straight bank, our predictive equation (Eqn. 1) provides a relatively good estimate of the increased erosion potential produced by logs. For type 2 logs, although we cannot determine the actual values of the changes in bank erosion, we can predict the direction of change based on the spacing, and distance from the bank, of the logs.

Hydraulics: Interactions between logs and irregular bank lines

Recirculation flows develop where the irregular bank line is sufficiently divergent from the downstream direction of the flow (Schmidt, Rubin, & Ikeda, 1993). The irregular bank line could be caused by natural features, such as debris fans (Schmidt et al., 1993) and the abutment stabilized by riparian vegetation (Pizzuto et al., 2010), and artificial structures like groynes (Uijttewaal, 2005). The irregularity of the bank can cause a negative pressure gradient relative to the main channel flow both upstream and downstream (Ettema & Muste, 2004). The flow experiencing this pressure gradient separates from the main channel flow and forms recirculation zones upstream and downstream of the irregularity (Engelhardt, Krüger, Sukhodolov, & Nicklisch, 2004; Safarzadeh, Salehi Neyshabouri, Ghodsian, & Zarrati, 2010; Uijttewaal, Lehmann, & Mazijk, 2001) which serves to weaken or reinforce the recirculation.

At our field site, the irregularity of the bank that induced recirculation flow was usually abutments associated with riparian trees (Rutherford and Grove, 2004). The field survey suggested that logs can weaken or reinforce the recirculation flow based

on whether the logs increase or decrease the near-bank velocity. If a log increases the near-bank velocity, such as a Type 1 log not far from the bank, the log creates a high velocity zone between the log and the abutment and reduces the negative pressure gradient near the abutment. In this case the log weakens the recirculation flow. Conversely, if a log decreases the near-bank velocity, such as a Type 2 log close to bank, then the log creates a low velocity zone between the log and the abutment and enhances the negative pressure gradient near the abutment. In this case, the log reinforces the recirculation flow.

Logs near a meander bend can generate complex flow patterns, and our observations of the flow patterns are consistent with previous field studies with similar conditions. Logs near the outer bank of a meandering bend can develop a slow flow zone near the bank (Daniels & Rhoads, 2007; Konsoer et al., 2016), that pushes the fast flow core associated with river bends toward the inner bank (Daniels & Rhoads, 2003; Konsoer et al., 2016), and induce recirculation flow near the bank (Daniels & Rhoads, 2004). Although the flow patterns around these logs are complicated and depend on the particular arrangement of the logs (Daniels & Rhoads, 2004), these logs generally function as permeable groynes and protect the bank (Kang, Yeo, Kim, & Ji, 2011; Uijttewaal, 2005).

The recirculation flow in a groyne field is usually considered much slower than the main channel flow, to induce deposition in the recirculation zone and protect the bank (Simpson, 1989; Sukhodolov, Uijttewaal, & Christof, 2002). Most of the

recirculation flow in our field site was much slower than the main channel flow.

However, the velocity of the backflow in the scallop bank near log C4 was as high as the approaching flow outside of the scallop. The recirculation flow, in this case, can potentially cause the same level of erosion as the main channel flow.

In summary, if a log accelerates the near-bank velocity (i.e. a Type 1 log not far from the bank), it weakens the recirculation flow, but, if a log decelerates the near-bank velocity (i.e. a Type 2 log close to bank), it reinforces the recirculation flow (Figure 14). Logs near the outer bank of a meander bend, even with a gap between the log and the bank, can function as groynes, decreasing the flow velocity between the logs and potentially protecting the bank. Further studies are needed to investigate 1) how sizes of recirculation flows and magnitudes of backflow velocities relate to various characteristics of logs and geomorphological settings, and 2) how the volume of bank erosion relates to the magnitude of recirculation flow. **(Figure 14 near here)**

Bank erosion around fallen logs

Several studies have observed increased local bank erosion around fallen trees or log jams in rivers (Frissell & Nawa, 1992; Keller & Swanson, 1979; Thompson, 2002, 2006). Other studies have described instream logs deflecting flow away from the bank (Brooks, Gehrke, Jansen, & Abbe, 2004; Brooks, Howell, Abbe, & Arthington, 2006; Segura & Booth, 2010). However, ours is the most substantial attempt to systematically measure the magnitude of erosion around instream logs and relate

the erosion rate to the hydraulics around the logs. This research, based on erosion pin measurements on 35 large logs in a rapidly eroding channel, demonstrated that, on average, logs did not statistically (or substantially) change bank erosion rates. Lester and Wright (2009) found similar results with smaller wood pieces (0.05 -0.35 m in diameter) that were placed in the channel. Their erosion rate after 18 months was about half of our rates, being 1.6 cm/yr for treatment sites and 1.1 cm/yr for control sites, but the difference between treatment and control sites was not statistically significant.

Logs did change the distribution of erosion on the bank face. Banks without logs tended to have higher erosion rates at the top of the bank, suggesting that this channel was widening from the top. This channel widening can be linked to the regulated flow (Tilleard et al., 1994). The logs tended to shift the erosion down the bank face, towards the bank toe, resulting in a parallel retreat of the bank. Daniels and Rhoads (2003) suggest that as the flow is deflected to the gap between the log and the bank the high velocity core expands but decreases in magnitude. MacVicar and Roy (2007) also demonstrate that the near-bank velocity shifts, from high near the water surface and low near the bed upstream of the log, to being more evenly distributed in the vertical direction downstream of the log. Thus the logs caused a parallel retreat of the bank.

Although average erosion rates were not affected by logs, when we consider the characteristics of logs, we find that logs in different categories can increase or

decrease local erosion rates in patterns that generally concur with near-bank changes predicted from the flume studies. Many of these changes have low statistical significance because of the small sample size of logs, but the directions of change are consistent and generally as predicted from the near-bank velocity.

Consistent with the flume studies, hydraulically isolated logs can increase bank erosion and hydraulically interacting logs caused no increase in bank erosion. However, even within the hydraulically interacting group of logs the pattern is not simple (Figure 12). From the flume studies, Zhang et al. (2019b) suggested that for hydraulically interacting logs, if the logs are close to the bank (gap width/log length=0.07), they can decrease the near-bank velocity, but if the logs are at an intermediate distance (gap width/log length=0.2) from the bank, they always increase near-bank velocity, and then near-bank velocity drops again as the logs move away. This is exactly the pattern of bank erosion rate we found with the logs, most of which were hydraulically interacting (Figure 12-3), where logs close to the bank did not increase bank erosion rates, whilst logs at an intermediate distance from the bank tended to increase the bank erosion rate.

Studies of instream wood often suggest that size, complexity and orientation of logs determines their degree of geomorphological and hydraulic effect (Gippel, O'Neill, & Finlayson, 1992; Hughes, 2011; Klaar et al., 2011; Roni et al., 2015). Our erosion data suggests that logs with larger blockage ratio have larger effect on bank erosion (as predicted from the flume results), but the direction of change depends on

the depth of flow. In Chambers Creek, the logs were emergent during the near-bankfull flow, so the logs could only deflect flow horizontally through the gap between the logs and the bank and thus increase bank erosion. However, logs were submerged during the flood in the second season, so most flow passed above or below the logs and the logs functioned as roughness elements reducing bank erosion overall. Konsoer et al. (2016) also observed that near-bank velocity during an overbank flood was less than that for a near-bankfull flow when there were abundant large logs along the bank. For this reason, they suggest that logs were effective at preventing the penetration of high velocity flow onto the bank face during floods.

Logs at right-angles to the flow (perpendicular) have been shown to cause the most hydraulic changes (Gippel, O'Neill, Finlayson, & Schnats, 1996; Zhang et al., 2019a). However, in our study, logs with oblique angles to the flow produced the most increase in bank erosion, while logs with perpendicular or parallel angles to the flow caused no change. Abbe & Montgomery (2003) and Mao, Andreoli, Comiti, & Lenzi (2008) describe a similar result in which bank erosion is associated with oblique 'flow deflection' log jams. Further investigations are needed to predict flow deflection by logs with different angles to the flow and associated bank erosion.

This research has implications for stream management and for returning a natural load of logs to rivers as part of stream restoration projects. In general, large logs have a modest influence on bank erosion rates. Concerns by landholders and

others that logs fallen into a river will cause dramatic bank erosion are misplaced. When logs are placed back into streams, if bank erosion is a concern, then it is better to place multiple logs at natural spacing than isolated logs. Hydraulically isolated logs (i.e. logs separated by more than around 30 root-plate diameters) are the most likely to cause local bank erosion around the log, and the blockage ratio of the log and distance between the bank and the log are the main predictors of the effect. This study suggests that it is better to place a log hard against the bank because this causes less flow deflection than when it is 2 – 5 m from the bank. So far, our results suggest that logs oblique to the flow cause more erosion than logs at right angles to the flow, but this result needs to be verified. Further, the hydraulic effect of the logs is greatest when the log is just covered by flow rather than at flood levels. At a more natural log-spacing (see discussion in Zhang et al., 2019b), as found in the River Murray, the hydraulic interaction of logs means that they would reduce near bank velocity and slightly reduce over-all bank erosion at reach scale. Finally, the complex flows between logs and the river bank, particularly in recirculating flows, will be relevant to understanding fish habitat.

Conclusions

This is the first substantial field study of the effect of logs on patterns and rates of river bank erosion. The study was possible because of seasonal high-flow irrigation releases from a dam on the River Murray in SE Australia. To evaluate on near-bank

velocities and flow patterns predictions made from qualitative observations and flume studies (Zhang et al., 2019a, 2019b), we measured velocity distributions around 11 large logs at a near-bankfull flow, as well as two years of field measurements of bank erosion rates around 35 large instream logs. The field measurements generally support the predicted results from the flume studies for both velocity and bank erosion. These results have implications for river managers, and for restoration projects that place logs back into rivers.

A single log can increase near-bank velocity, and this near-bank velocity increase can be well predicted from the blockage ratio of the log and distance between the log and the bank when the log is adjacent to a straight bank. The hydraulic interactions between successive logs tended to reduce this increase or even decrease the near-bank velocity. This effect accumulates downstream along the multiple logs.

Logs adjacent to curved banks can interact with the recirculation flow in the curved bank and generate complex flow patterns. When a single log increases near-bank velocity, it will weaken the recirculation flow, whereas when a series of logs progressively decreases near-bank velocity, downstream logs in this series can reinforce the recirculation flow when they are adjacent to a curved bank. Multiple logs located near the outer bank of meander bends can function as permeable groynes, creating slow flow zones between the logs and protecting the bank.

On average, the erosion rate around logs in this study were not statistically different from the erosion rate at nearby controls. However, logs tended to shift the erosion from bank top to bank toe, resulting in a parallel retreat of the bank face. Individual logs can increase or decrease local bank erosion in patterns that are generally consistent with the near-bank velocity changes caused by the logs. Hydraulic interaction between the logs is a major factor that controls the effect of instream logs on bank erosion. Hydraulically isolated logs can increase bank erosion rate, whilst hydraulically interacting log causes no changes or decrease bank erosion.

The hydraulic interaction between the logs can overwhelm the effect of log size and form/complexity, so that hydraulically interacting logs with different size and/or form produce similar hydraulic and geomorphic changes. Hydraulic interactions also influence the effect of distance between the log and bank. With hydraulic interactions, logs do not increase bank erosion rate when they are close to the bank but greatly increase rates when they move to intermediate distance from the bank.

We provided a framework to systematically investigate the effect of instream logs adjacent to a curved bank in this study. Further studies are needed to investigate how logs interact with recirculation flows, and also to investigate how logs affect hydraulics and bank erosion as a newly fallen log progressively simplifies its

morphology over time. This study was carried out with a particular type of log and hydraulic setting. This can be extended to log jams and different wood types.

References

- Abbe, T. B., & Montgomery, D. R. (2003). Patterns and processes of wood debris accumulation in the Queets river basin, Washington. *Geomorphology*, 51(1), 81-107.
- Abbe, T. B., Montgomery, D. R., & Petroff, C. (1997). *Design of stable in-channel wood debris structures for bank protection and habitat restoration: an example from the Cowlitz River, WA*. Paper presented at the Conference on Management of Disturbed by Channel Incision, University of Mississippi, Oxford, USA. 809-815
- Abernethy, B., & Rutherford, I. (2001). The distribution and strength of riparian tree roots in relation to riverbank reinforcement. *Hydrological processes*, 15(1), 63-79.
- Boland, D. J., Brooker, M. I. H., Chippendale, G. M., Hall, N., Hyland, B. P. M., Johnston, R. D., . . . Turner, J. D. (2006). *Forest trees of Australia*. Melbourne: Nelson and CSIRO.
- Brooks, A. P., Gehrke, P. C., Jansen, J. D., & Abbe, T. B. (2004). Experimental reintroduction of woody debris on the Williams River, NSW: geomorphic and ecological responses. *River Research and Applications*, 20(5), 513-536.
- Brooks, A. P., Howell, T., Abbe, T. B., & Arthington, A. H. (2006). Confronting hysteresis: wood based river rehabilitation in highly altered riverine landscapes of south-eastern Australia. *Geomorphology*, 79(3-4), 395-422.
- Collins, B. D., Montgomery, D. R., Fetherston, K. L., & Abbe, T. B. (2012). The floodplain large-wood cycle hypothesis: A mechanism for the physical and biotic structuring of temperate forested alluvial valleys in the North Pacific coastal ecoregion. *Geomorphology*, 139, 460-470.
- Corenblit, D., Tabacchi, E., Steiger, J., & Gurnell, A. M. (2007). Reciprocal interactions and adjustments between fluvial landforms and vegetation dynamics in river corridors: A review of complementary approaches. *Earth-Science Reviews*, 84(1-2), 56-86.

- Couper, P., Stott, T., & Maddock, I. (2002). Insights into river bank erosion processes derived from analysis of negative erosion-pin recordings: observations from three recent UK studies. *Earth Surface Processes and Landforms*, 27(1), 59-79.
- Daniels, M. D., & Rhoads, B. L. (2003). Influence of a large woody debris obstruction on three-dimensional flow structure in a meander bend. *Geomorphology*, 51(1), 159-173.
- Daniels, M. D., & Rhoads, B. L. (2004). Effect of large woody debris configuration on three-dimensional flow structure in two low-energy meander bends at varying stages. *Water resources research*, 40(11), W11302.
- Daniels, M. D., & Rhoads, B. L. (2007). Influence of experimental removal of large woody debris on spatial patterns of three-dimensional flow in a meander bend. *Earth Surface Processes and Landforms*, 32(3), 460-474.
- Dietrich, W. E., & Whiting, P. J. (1989). Boundary shear stress and sediment transport in river meanders of sand and gravel. *River Meandering*, 12, 1-50.
- Engelhardt, C., Krüger, A., Sukhodolov, A., & Nicklisch, A. (2004). A study of phytoplankton spatial distributions, flow structure and characteristics of mixing in a river reach with groynes. *Journal of Plankton Research*, 26(11), 1351-1366.
- Ettema, R., & Muste, M. (2004). Scale Effects in Flume Experiments on Flow around a Spur Dike in Flatbed Channel. *Journal of hydraulic engineering*, 130(7), 635-646.
- Frissell, C. A., & Nawa, R. K. (1992). Incidence and causes of physical failure of artificial habitat structures in streams of western Oregon and Washington. *North American Journal of Fisheries Management*, 12(1), 182-197.
- Gippel, C. J. (1995). Environmental hydraulics of large woody debris in streams and rivers. *Journal of environmental engineering*, 121(5), 388-395.
- Gippel, C. J., O'Neill, I. C., & Finlayson, B. L. (1992). *The hydraulic basis of snag management*. Melbourne: Centre for Environmental Applied Hydrology, Department of Civil and Agricultural Engineering, University of Melbourne.
- Gippel, C. J., O'Neill, I. O., Finlayson, B. L., & Schnats, I. (1996). Hydraulic guidelines for the re-introduction and management of large woody debris in lowland rivers. *regulated rivers: research & management*, 12(2-3), 223-236.
- Gurnell, A. M. (2014). Plants as river system engineers. *Earth Surface Processes and Landforms*, 39(1), 4-25.

- Gurnell, A. M., Bertoldi, W., & Corenblit, D. (2012). Changing river channels: The roles of hydrological processes, plants and pioneer fluvial landforms in humid temperate, mixed load, gravel bed rivers. *Earth-Science Reviews*, 111(1-2), 129-141.
- Gurnell, A. M., Piégay, H., Swanson, F. J., & Gregory, S. V. (2002). Large wood and fluvial processes. *Freshwater Biology*, 47, 601-619.
- Gurnell, A. M., & Sweet, R. (1998). The distribution of large woody debris accumulations and pools in relation to woodland stream management in a small, low - gradient stream. *Earth Surface Processes and Landforms: The Journal of the British Geomorphological Group*, 23(12), 1101-1121.
- Henshaw, A. J., Thorne, C. R., & Clifford, N. J. (2012). Identifying causes and controls of river bank erosion in a British upland catchment. *Catena*, 100, 107-119.
- Hughes, V. (2011). *Hydraulic habitat in the River Murray: the influence of geomorphology and large wood*. (Doctor of Philosophy), Canberra: University of Canberra.
- Kang, J., Yeo, H., Kim, S., & Ji, U. (2011). Experimental investigation on the local scour characteristics around groynes using a hydraulic model. *Water and environment journal*, 25, 181-191.
- Keller, E. A., & Swanson, F. J. (1979). Effect of large organic material on channel form and fluvial processes. *Earth surface processes*, 4(4), 361-380.
- Klaar, M. J., Hill, D. F., Maddock, I., & Milner, A. M. (2011). Interactions between instream wood and hydrogeomorphic development within recently deglaciated streams in Glacier Bay National Park, Alaska. *Geomorphology*, 130(3-4), 208-220.
- Knighton, D. W., & Macdonald, J. A. (1979). Hydraulic resistance of artificial strip roughness. *Journal of the Hydraulics Division*, 105(6), 675-690.
- Koehn, J. D., Nicol, S. J., & Fairbrother, P. S. (2004). Spatial arrangement and physical characteristics of structural woody habitat in a lowland river in south-eastern Australia. *Aquatic Conservation: Marine and Freshwater Ecosystems*, 14(5), 457-464.
- Konsoer, K. M., Rhoads, B. L., Best, J. L., Langendoen, E. J., Abad, J. D., Parsons, D. R., & Garcia, M. H. (2016). Three-dimensional flow structure and bed morphology in large elongate meander loops with different outer bank roughness characteristics. *Water resources research*, 52(12), 9621-9641.

- Lawler, D. M. (1987). Bank erosion and frost action: an example from South Wales. *International Geomorphology 1986, Part 1*, 575-590.
- Lawler, D. M. (1993). The measurement of river bank erosion and lateral channel change: a review. *Earth Surface Processes and Landforms*, 18(9), 777-821.
- Lawler, D. M., Grove, J. R., Couperthwaite, J. S., & Leeks, G. J. L. (1999). Downstream change in river bank erosion rates in the Swale–Ouse system, northern England. *Hydrological processes*, 13(7), 977-992.
- Lester, R. E., & Wright, W. (2009). Reintroducing wood to streams in agricultural landscapes: changes in velocity profile, stage and erosion rates. *River Research and Applications*, 25(4), 376-392.
- MacVicar, B. J., & Roy, A. G. (2007). Hydrodynamics of a forced riffle pool in a gravel bed river: 1. Mean velocity and turbulence intensity. *Water Resources Research*, 43(12).
- Mao, L., Andreoli, A., Comiti, F., & Lenzi, M. A. (2008). Geomorphic effects of large wood jams on a sub-antarctic mountain stream. *River Research and Applications*, 24(3), 249-266.
- Montgomery, D. R., Buffington, J. M., Smith, R. D., Schmidt, K. M., & Pess, G. (1995). Pool spacing in forest channels. *Water resources research*, 31(4), 1097-1105.
- Morris, H. M. (1955). Flow in rough conduits. *Transactions of the American Society of Civil Engineers*, 120(1), 373-398.
- Mutz, M. (2000). Influences of woody debris on flow patterns and channel morphology in a low energy, sand-bed stream reach. *International review of hydrobiology*, 85(1), 107-121.
- Nearmap. 2018. Parlour Creek and Chambers Creek, 35°59'59" S, 146°40'29" E, elevation 146.7m. Photomap, vertical layer. [accessed 2019 Oct 21]. <http://maps.au.nearmap.com>.
- Pilotto, F., Bertoincin, A., Harvey, G. L., Wharton, G., & Pusch, M. T. (2014). Diversification of stream invertebrate communities by large wood. *Freshwater Biology*, 59(12), 2571-2583.
- Pizzuto, J., O'Neal, M., & Stotts, S. (2010). On the retreat of forested, cohesive riverbanks. *Geomorphology*, 116(3-4), 341-352.
- Pollen-Bankhead, N., & Simon, A. (2009). Enhanced application of root-reinforcement algorithms for bank-stability modeling. *Earth Surface Processes and Landforms*, 34(4), 471-480.

- Roni, P., Beechie, T., Pess, G., Hanson, K., & Jonsson, B. (2015). Wood placement in river restoration: fact, fiction, and future direction. *Canadian journal of fisheries and aquatic sciences*, 72(3), 466-478.
- Rutherford, I. D., & Grove, J. R. (2004). The influence of trees on stream bank erosion. *Riparian Vegetation and Fluvial Geomorphology*, 8, 141-152.
- Safarzadeh, A., Salehi Neyshabouri, S. A. A., Ghodsian, M., & Zarrati, A. R. (2010). *Experimental study of head shape effects on shear stress distribution around a single groyne*. Paper presented at the River flow, Braunschweig, Germany.
- Schmidt, J. C., Rubin, D. M., & Ikeda, H. (1993). Flume simulation of recirculating flow and sedimentation. *Water resources research*, 29(8), 2925-2939.
- Segura, C., & Booth, D. B. (2010). Effects of geomorphic setting and urbanization on wood, pools, sediment storage, and bank erosion in Puget Sound streams. *Journal of the American water resources association*, 46(5), 972-986.
- Shields, F. D., & Gippel, C. J. (1995). Prediction of effects of woody debris removal on flow resistance. *Journal of hydraulic engineering*, 121(4), 341-354.
- Simpson, R. L. (1989). Turbulent boundary-layer separation. *Annual Review of Fluid Mechanics*, 21(1), 205-232.
- Sukhodolov, A. N., Uijttewaals, W. S. J., & Christof, E. (2002). On the correspondence between morphological and hydrodynamical patterns of groyne fields. *Earth Surface Processes and Landforms*, 27(3), 289-305.
- Thompson, D. M. (2002). Long-Term Effect of Instream Habitat-Improvement Structures on Channel Morphology Along the Blackledge and Salmon Rivers, Connecticut, USA. *Environmental Management*, 29(2), 250-265.
- Thompson, D. M. (2006). Did The Pre-1980 Use Of In-Stream Structures Improve Streams? A Reanalysis Of Historical Data. *Ecological Applications*, 16(2), 784-796.
- Tilleard, J., Erskine, W., & Rutherford, I. (1994). Impacts of River Murray flow regulation on downstream channel morphology. *Water Down Under 94: Surface Hydrology and Water Resources Papers; Preprints of Papers*, 409.
- Uijttewaals, W. S. (2005). Effects of groyne layout on the flow in groyne field: laboratory experiments. *Journal of hydraulic engineering*, 131(9), 782-791.
- Uijttewaals, W. S., Lehmann, D. V., & Mazijk, A. V. (2001). Exchange processes between a river and its groyne fields: Model experiments. *Journal of hydraulic engineering*, 127(11), 928-936.

Wallerstein, N. P., Alonso, C. V., Bennett, S. J., & Thorne, C. R. (2001). Distorted Froude-scaled flume analysis of large woody debris. *Earth Surface Processes and Landforms*, 26(12), 1265-1283.

White, K. (1998). *Comparison of the characteristics of large woody debris found in streams in the Pacific northwest and southeastern Australia*. (Literature review submitted as partial fulfilment of BSc (Honours)), Melbourne: University of Melbourne.

Zhang, N., Rutherford, I. D., & Ghisalberti, M. (2019a). Effect of instream logs on bank erosion potential: a flume study with a single log. *Journal of Ecohydraulics*, 1-14. DOI:10.1080/24705357.2019.1634499

Zhang, N., Rutherford, I. D., & Ghisalberti, M. (2019b). The effect of instream logs on bank erosion potential: a flume study with multiple logs. *Journal of Ecohydraulics*, 1-14. DOI:10.1080/24705357.2019.1669495

Acknowledgements

We acknowledge the generous financial and field support provided by the NSW government through the Soil Conservation Service (River Murray Works) (part of Local Land Services, and, in particular, we would like to thank Ben Berry from that office for his consistent assistance and enthusiasm for this work. We would like to thank the landholders in the field area for providing access to their properties: Morebringer, Negarie, Mayfield Cottage, Mayfield and Shrublands. Thanks for the field support provided by Alex Sims, Walter Box, Darren Hocking, Jeremy Lee, Elyssa De Carli and Jorge Maldonado. Thanks also to James Grove, Mike Sammonds and Iwona Conlan for advice on survey methods. The Department of Infrastructure Engineering, University of Melbourne provided the ADCP. The first author was supported by a postgraduate scholarship provided by the Australian government.

Data availability statement

The data sets used and/or analyzed during the current study are available from the corresponding author on reasonable request.

Disclosure statement

The authors have no conflict of interest.

Figure Captions

Figure 1: Parlour Creek: an anabranching channel of the River Murray (Nearmap imagery, 2018). Yellow dots indicate locations of surveyed logs.

Figure 2: Instream logs in Parlour Creek, SE Australia (looking downstream). (Boat on right for scale, $36^{\circ}0'23''$ S, $146^{\circ}39'56''$ E).

Figure 3: Water level at the city of Albury from Sep 2015 to Jun 2017 (data from Murray Darling Basin Authority website) (Albury is upstream of Parlour Creek on the main channel and is the closest gauging station).

Figure 4: Erosion pin setup and location of points where near-bank velocity distribution was measured.

Figure 5: Erosion pins and measurements method. 1) photo of erosion pins. 2) Measuring erosion pins around logs. 3) sketch illustrating the measurement method for erosion pins.

Figure 6: Comparison of near-bank velocity around logs: upstream (grey bar), downstream (black bars) and predicted downstream (hollow bars). For log C3, the upstream velocity could not be measured within the distance between the log and bank due to the low flow depth. The dashed grey bar indicates the velocity closest to

the bank that we could measure upstream of log C3 and the dashed hollow bar indicates the predicted downstream velocity based on the upstream velocity indicated by the dashed grey bar. We made no predictions for logs associated with recirculation flows.

Figure 7: Depth averaged velocity distribution near the bank along log S2, M3 and C5. Solid arrows indicate depth averaged velocity. Dashed arrows indicate the flow pattern that was deduced from the depth averaged velocity. The orange logs are logs that recently fell into the river in 2016.

Figure 8: Depth averaged velocity distribution near the bank along C3. Solid arrows indicate depth averaged velocity.

Figure 9: Interactions between instream logs and recirculating flows. 1) Log C6 far from the bank had no influence on the recirculation. 2) Log C4 increased the near-bank velocity and weaken the recirculation near the log. 3) Log C5 decreased the near-bank velocity and reinforce the recirculation near the log. Solid arrows indicate depth averaged velocity. Dashed arrows indicate flow pattern that was deduced from depth averaged velocity.

Figure 10: Depth averaged velocity distribution near the bank along log C1 and C2. Log C1 and C2 located near the outer bank of a meander bend and functioned in the same way as groynes. A slow flow zone formed between the logs, and recirculation zones formed between the logs and the bank. Solid arrows indicate depth averaged

velocity. Dashed arrows indicate the flow pattern deduced from the depth averaged velocity.

Figure 11: Average bank erosion rate 1) for all logs; 2) and 3) in different vertical positions (top to bottom indicates bank top to bank toe); 4) and 5) in different streamwise positions (top to bottom indicates upstream to downstream).

Figure 12: Relative bank erosion rate (around log/control) with categories of 1) channels, 2) hydraulic interactions, 3) distances from the bank, 4) angles to flow. The value of relative bank erosion rate less than one indicates logs decreased erosion rate and more than one indicates logs increased bank erosion rate. Attach= 0 m, 0 m < close $\leq$ 2 m, 2 m < intermediate $\leq$ 5 m, far > 5 m. 0 $\leq$ parallel $\leq$ 30, 30 < oblique $\leq$ 60, 60 < perpendicular $\leq$ 90 (degrees).

Figure 13: bank profile changes between the upstream and downstream cross-sections for log S1, S2 and C3. The logs indicate the position of the root plate relative to the bank where the vertical axis indicates the bank at upstream cross-section. The horizontal axis denotes the water level at the survey.

Figure 14: Summary of the effect of logs on near bank velocity and recirculation flow. Red arrows indicate near-bank velocity changed by instream logs and the size of the arrows relative to the approaching flow indicated the magnitude of the velocity changes.

Tables

Table 1: Value of factors (defined in Eqn. 1) to predict the near-bank velocity around a single log.

Normalised distance from the bank (gap width/log length)	<i>n</i>	<i>m</i>	p-value
0.07	6.24	-0.72	0.001
0.13	4.66	-0.51	0.012
0.20	2.40	-0.08	0.004
0.33	1.82	-0.03	0.013

Table 2: Values of factors (defined in Eqn. 3) to predict the near-bank velocity around a Type 2 log

Spacing (root plate diameter)	Distance from bank (gap width/log length)	<i>a</i>	<i>b</i>	<i>c</i>	Spearman's Correlation coefficient
Small spacing (1.3-3.3)	Intermediate (0.2)	-	-	1	-*
Medium spacing (10-17)	Intermediate (0.2)	0.75	0.02	0.00	0.89**
Large spacing (27-)	Intermediate (0.2)	-	-	1	-*
Small spacing (1.3-3.3)	Close (0.07)	1.17	0.05	-0.51	0.97**
Medium spacing (10-17)	Close (0.07)	1.01	0.03	-0.35	0.94**
Large spacing (27-)	Close (0.07)	-	-	1	-*

*The factors were determined as the log functions as a single log.

**Correlation is significant at the 0.01 level (2-tailed).

ESP_4838_F1.tif

ESP_4838_F2.tiff

ESP_4838_F3.tif

ESP_4838_F4.tif

1) Erosion pin

2) Setting up erosion pins

3) Measurement

ESP_4838_F5.tif

ESP_4838_F6.tif

ESP_4838_F7.tif

ESP_4838_F8.tif

ESP_4838_F9.tif

ESP_4838_F10.tif

ESP_4838_F11.tif

ESP_4838_F12.tif

ESP_4838_F13.tif

ESP_4838_F14.tif

ESP_4838_Graphicalinformation_figure.tif